

2002 Monaco Signature 40 Centurion

<http://www.DreamFindersRV.com/RV/7708291/details.htm>

I am including the last service report on the coach done last year.

This is a summary of the coach's history:

The Signature has been our third coach, we have kept it because we have really enjoyed it. I am 80 this year,,we believe it is time to travel using a different method now.

For your information the coach has never been in an accident.

The windshield is like new, was replaced a few years ago because of a rock damage.

Four years ago a hydraulic fluid leak ended up with insurance covering the re carpeting of the bay compartments.....they look brand new.

House batteries (4) Replaced in 2013.

Engine batteries (2) replaced in 2014.

2 tires were replaced in 2013.

4 tires were replaced in 2014.

Firestone Fire Tire Company checks and adjusts tire pressure prior to trips.

The alternator was replaced in 2014.

Aqua hot was serviced in 2013

The plastic protective coating on the front of the coach under the windshield will need to be removed and replaced at some time. It has done it's job, but is now starting to 'craze' ...however it still offers protection to the paint surface and could be left in place.

About 4 years ago I replaced the front TV with a 'flat screen' model. In the process I modified the TV cabinet reducing how much it extended into the vehicle by about 5 inches, which really improved the headroom as you enter the door and the stairs.

About 20 of the ceiling lights have replaced with LED bulbs for greater efficiency of battery use.

The coach has always been under cover and protected from the sun.

The coach is regularly washed and polished by a man who works for me.

I hope this gives you some idea as to how the coach has been cared for. Any further questions...please E-mail....